


# AI-2025-A40-B40-C80,共10套

The position of the four pillars is the same .no offset



Only need one eyebolt hole in the B Plate.

No screw holes in the ejector plate, and don't need to make return pin holes